


RIAI ACCREDITED CONSERVATION ARCHITECTS GRADE I

## THE MALONE MAUSOLEUM,

## KILBIXY, Co WESTMEATH



Conservation Report APPENDIX 2: DRAWINGS and PHOTOGRAPHIC SURVEY

22 South William Street, Dublin D02 H394 Tel. 01 677 1006 email: richard@lotts.ie www.lotts.ie D i r e c t o r s Desmond Byrne BArch MRIAI Richard McLoughlin BArch MSc MRIAI Registered in Ireland no. 408083 - VAT no. 6428083T

THE MALONE MAUSOLEUM, KILBIXY CO. WESTMEATH	Location: Context	Inventory Ref No.
PHOTOGRAPHIC SURVEY		N/A
Notes:		



THE MALONE MAUSOLEUM, KILBIXY CO. WESTMEATH	Location: Pyramid roof detail	Inventory Ref No.
PHOTOGRAPHIC SURVEY		
Notes:	· · ·	· · · · · · · · · · · · · · · · · · ·



THE MALONE MAUSOLEUM, KILBIXY CO. WESTMEATH	Location: Pyramid roof detail	Inventory Ref No
PHOTOGRAPHIC SURVEY		




Widespread vegetation growth to base of pyramid

Stone blocks removed to upper pyramid during opening up works 2022

Stone blocks removed to lower pyramid during opening up works 2022

THE MALONE MAUSOLEUM, KILBIXY CO. WESTMEATH	Location: Opening works of pyramid	Inventory Ref
PHOTOGRAPHIC SURVEY		N/A
Notes:		







THE MALONE MAUSOLEUM, KILBIXY CO. WESTMEATH	Location: Interior of pyramid	Inventory Ref
PHOTOGRAPHIC SURVEY		N/A
Notor	·	•




THE MALONE MAUSOLEUM, KILBIXY CO. WESTMEATH	Location: Front (North-east) Elevation	Inventory Ref N
PHOTOGRAPHIC SURVEY		N/A
Notos	•	



THE MALONE MAUSOLEUM, KILBIXY CO. WESTMEATH	Location: Side (South-east) Elevation	Inventory Ref No.
PHOTOGRAPHIC SURVEY		N/A
Notes:		




	Location: Side (South-west) Elevation	Inventory Re
THE MALONE MAUSOLEUM, KILBIXY CO. WESTMEATH		N/A
PHOTOGRAPHIC SURVEY		
Notes:		







THE MALONE MAUSOLEUM, KILBIXY CO. WESTMEATH	Location: Side (North-west) Elevation	Inventory Re
PHOTOGRAPHIC SURVEY		N/A
Notes:	·	·





THE MALONE MAUSOLEUM, KILBIXY CO. WESTMEATH	Location: Railings	Inventory Ref N
PHOTOGRAPHIC SURVEY		N/A
Notes:	·	





THE MALONE MAUSOLEUM, KILBIXY CO. WESTMEATH		Location: Paving to	Location: Paving to threshold		10.
PHOTOGRAPHIC SURVEY					
Notes:					
		the states		S. KING BAR	
		I I I			
				· · ·	

Stone paving inside entrance gates to north-east View of cracked paving slabs to north-east side View of paving slabs to south-east elevation View of stone paving slabs to north-west side



Photographic Survey page 12 of 16

## THE MALONE MAUSOLEUM, KILBIXY CO. WESTMEATH

Location: Interior

Inventory Ref No.


PHOTOGRAPHIC SURVEY

Notes:

Interior of mausoleum showing extensive water ingress Detailing of slate sarcophagus and memorial slab slate sarcophagus and memorial slab SE

Vault detailing with central vent

Interior of mausoleum showing extensive water ingress View through entrance doors to mausoleum interior



View of interior of mausoleum door

THE MALONE MAUSOLEUM, KILBIXY CO. WESTME	ATH Location: Interior details	Inventory Ref N
PHOTOGRAPHIC SURVEY		





THE MALONE MAUSOLEUM, KILBIXY CO. WESTMEATH	Location: Burial crypt	Invento
PHOTOGRAPHIC SURVEY		

